

TEL : 82-32-880-0256  
FAX : 82-32-889-5905  
AFS : RKRRYNYX  
E-mail : aisd@molit.go.kr  
Web : http://ais.casa.go.kr

**REPUBLIC OF KOREA**  
**Ministry of Land, Infrastructure and Transport**  
**Office of Civil Aviation**  
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

**AIRAC**  
**AIP**  
**Supplement 5/19**  
**14 MAR 2019**

**GEN : NIL**

**ENR : NIL**

**A D : SEOUL/Gimpo INTL(RKSS)**

## OPERATIONAL RESTRICTIONS

### 1. INTRODUCTION

TCLL(Taxiway Center Line Light) for TWY B1 and P at Gimpo Airport will be phased unserviceable due to replacement.


### 2. PERIOD

From 1400 UTC 25 APR 2019 To 2100 UTC 31 JUL 2019 (Detail unserviceable period as below)

### 3. WORKING AREAS (See the diagram below)

#### Diagram

#### <LIGHTING AIDS RWY 14R/32L AND 14L/32R AND EXIT TWY>



TCLL for B1 Unserviceable  
① <201904251400 ~ 201906102100>

TCLL for P Unserviceable  
② <201906111400 ~ 201907312100>

### 4. REMARKS

- (1) TCLL(Taxiway Center Line Light) for TWY B1 is unserviceable From 25 APR 2019 To 10 JUN 2019 irrespective of working hours.
- (2) TCLL(Taxiway Center Line Light) for TWY P is unserviceable From 11 JUN 2019 To 31 JUL 2019 irrespective of working hours.
- (3) If Low visibility procedures operated in case of less than 350 m, follow me car service will be provided for aircraft using area ① and ②.
- (4) After termination of the daily scheduled flight, work will begin.
- (5) Any change to the contents of this page will be notified by NOTAM.