

TEL : 82-32-880-0256
FAX : 82-32-889-5905
AFS : RKRRYNYX
E-mail : aisd@molit.go.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 8/19
9 MAY 2019

GEN : NIL

ENR : NIL

A D : SEOUL/Gimpo INTL(RKSS)

UNSERVICEABILITY OF ALS FOR RWY 32R

1. INTRODUCTION

The ALS(Approach Lighting Systems) for RWY 32R at Gimpo Airport will be unserviceable due to replacement.

2. PERIOD


From 1400 UTC 21 JUN 2019 To 2100 UTC 20 OCT 2019

3. WORKING AREA (See the diagram below)

A distance of construction is 900 m from the RWY 32R threshold.

Diagram

<LIGHTING AIDS RWY 14R/32L AND 14L/32R AND EXIT TWY>



4. REMARKS

- (1) ALS for RWY 32R unserviceable all period From 1400 UTC 21 JUN 2019 To 2100 UTC 20 OCT 2019 irrespective of working hours.
- (2) During the period, landing weather minima changed as [AIP RKSS AD CHART 2-35, 2-36, 2-37].
- (3) Any change to the contents of this page will be notified by NOTAM.