

TEL : 82-32-880-0256
 FAX : 82-32-889-5905
 AFS : RKRRYNYX
 E-mail : aisd@molit.go.kr
 Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
 11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 23/19
19 DEC 2019

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

TEMPORARY OBSTACLE ERECTED

1. INTRODUCTION

The obstacles will be existing on the east side of RWY 15L/33R of Incheon INTL Airport.
 ※ The obstacles are located about 4 322 m east from the centerline of RWY 15L/33R.

2. PERIOD

From 1500 UTC 29 JAN 2020 To 1500 UTC 30 DEC 2020

3. WORKING AREA

Position		OBST Type	Height		Radius	Remarks
			AGL	AMSL		
37°28'40.95"N	126°30'26.48"E	Tower crane	84.28 m	92.08 m	65 m	Lighted
37°28'43.85"N	126°30'24.68"E		98.20 m	106.00 m	50 m	
37°28'43.96"N	126°30'28.90"E		84.22 m	92.02 m	55 m	
37°28'46.18"N	126°30'26.45"E		92.39 m	100.19 m	48 m	
37°28'47.88"N	126°30'23.86"E		88.97 m	96.77 m	55 m	
37°28'48.28"N	126°30'20.97"E		89.42 m	97.22 m	60 m	
37°28'45.87"N	126°30'21.73"E		96.15 m	103.95 m	55 m	
37°28'45.19"N	126°30'18.07"E		85.22 m	93.02 m	55 m	
37°28'43.30"N	126°30'20.82"E		88.37 m	96.17 m	60 m	
37°28'41.28"N	126°30'23.01"E		98.20 m	106.00 m	50 m	

4. REMARKS

- (1) Tower cranes turn on their axis.
- (2) These tower cranes penetrate the conical surface of RKSI.
- (3) Lights will be installed on the top of the tower cranes.
- (4) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

