

TEL : 82-32-880-0256  
 FAX : 82-32-889-5905  
 AFS : RKRRYNYX  
 E-mail : aisd@molit.go.kr  
 Web : http://ais.casa.go.kr

**REPUBLIC OF KOREA**  
**Ministry of Land, Infrastructure and Transport**  
**Office of Civil Aviation**  
 11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

**AIRAC**  
**AIP**  
**Supplement 3/20**  
**12 MAR 2020**

**GEN : NIL**

**ENR : NIL**

**A D : SEOUL/Gimpo INTL(RKSS)**

**OPERATIONAL RESTRICTIONS**


**1. INTRODUCTION**

TCLL(Taxiway center line light) for TWY E2 at Gimpo INTL Airport will be phased unserviceable due to replacement.

**2. PERIOD**

From 1400 UTC 23 APR 2020 To 2100 UTC 22 MAY 2020

**3. WORKING AREAS** (See the diagram below)



Location	Period	Working hours (UTC)
TWY E2	23 APR 2020 ~ 22 MAY 2020	1400 ~ 2100 Daily

**4. REMARKS**

- (1) TCLL(Taxiway Center Line Light) for TWY E2 is unserviceable From 23 APR 2020 To 22 MAY 2020 irrespective of working hours.
- (2) If Low visibility procedures operated in case of less than 350 m, follow me car service will be provided for aircraft using area E2.
- (3) After termination of the daily scheduled flight, work will begin.
- (4) Any change to the contents of this page will be notified by NOTAM.