

TEL : 82-32-880-0256  
 FAX : 82-32-889-5905  
 AFS : RKRRYNYX  
 E-mail : aisd@molit.go.kr  
 Web : http://ais.casa.go.kr

**REPUBLIC OF KOREA**  
**Ministry of Land, Infrastructure and Transport**  
**Office of Civil Aviation**  
 11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

**AIRAC**  
**AIP**  
**Supplement 4/20**  
**9 APR 2020**

**GEN : NIL**

**ENR : NIL**

**A D : SEOUL/Gimpo INTL(RKSS)**

**OPERATIONAL RESTRICTIONS**

**1. INTRODUCTION**

TCLL(Taxiway center line light) for TWY P at Gimpo INTL Airport will be phased unserviceable due to replacement


**2. PERIOD**

From 1400 UTC 25 MAY 2020 To 2100 UTC 23 JUN 2020  
 (Detail unserviceable period as below)

**3. WORKING AREAS** (See the diagram below)

**Diagram**

<Lighting aids RWY 14R/32L and 14L/32R and exit TWY>



TCLL for P-P Unserviceable

Location	Period	Working hours (UTC)
TWY P	25 MAY 2020 ~ 23 JUN 2020	1400 ~ 2100 Daily

**4. REMARKS**

- (1) TCLL(Taxiway center line light) for TWY P is unserviceable From 25 MAY 20 To 23 JUN 2020 irrespective of working hours.
- (2) During the unserviceable period, low visibility procedure will be changed.  
 (See the 5. Low visibility procedure)
- (2) If low visibility procedures operated in case of less than 350 m, follow me car service will be provided for "F" aircraft using area ①.
- (3) After termination of the daily scheduled flight, work will begin.
- (4) Any change to the contents of these pages will be notified by NOTAM.

5. LOW VISIBILITY PROCEDURE

	DEPARTURE	ARRIVAL
<p>32R/L</p>		
<p>14R/L</p>		