

TEL : 82-32-880-0256
 FAX : 82-32-889-5905
 AFS : RKRRYNYX
 E-mail : aisd@molit.go.kr
 Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
 11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 5/20
7 MAY 2020

GEN : NIL

ENR : NIL

A D : SEOUL/Gimpo INTL(RKSS)

OPERATIONAL RESTRICTIONS


1. INTRODUCTION

TCLL(Taxiway center line light) for part of RWY 14L/32R between TWY D2 and D3 at Gimpo INTL Airport will be phased unserviceable due to replacement.

2. PERIOD

From 1400 UTC 24 JUN 2020 To 2100 UTC 21 AUG 2020
 (Detail unserviceable period as below)

3. WORKING AREA (See the diagram below)



Location	Period	Working hours (UTC)
Part of RWY 14L/32R	24 JUN 2020 ~ 21 AUG 2020	1400 ~ 2100 Daily

4. REMARKS

- (1) Part of TCLL(Taxiway center line light) for TWY D1, D2 and D3 is unserviceable From 24 JUN 2020 To 21 AUG 2020 irrespective of working hours. (See the No. 5 floor plan)
- (2) After termination of the daily scheduled flight, work will begin.
- (3) Any change to the contents of these pages will be notified by NOTAM.

5. FLOOR PLAN

