

TEL : 82-53-668-0255
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aais@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 7/21
6 MAY 2021

GEN : NIL

ENR : NIL

A D : SEOUL/Gimpo INTL(RKSS)

OPERATIONAL RESTRICTIONS

1. INTRODUCTION

- (1) TWYs(P6, N1, N3, N5) temporarily change to ACFT stand.
(See the No.5 Diagram)
- (2) RKSS AD 2-11 2.3.1 will be temporarily changed.
(See the No.3)

2. PERIOD

From 1400 UTC 31 MAY 2021 To 1400 UTC 31 DEC 2021

3. TEMPORARY CHANGE OF RKSS AD

Paragraph	Current	Change	Remark
AD 2-11 2.3.1	All aircraft on P5 should wait at the waiting point on P5 if N1, N2, N3, or N4 is occupied by any aircraft.	All aircraft on P5 should wait at the waiting point on P5 if N1, N2, N3, or N4 is occupied by any aircraft. <u>Exceptionally, if C class aircraft or below is parked on TWY N1, N3 aircraft taxiing and towing movement through P5 is possible.</u>	

4. REMARKS

- (1) If C class ACFT or below is parked on TWYs N1 and N3, ground taxiing or towing is available through TWY P5.
- (2) When using de-icing pad, TWY N1 is not available for ACFT parking.
- (3) The ACFT to be parked to TWYs P6, N1, N3 and N5 should be moved by towing car.
And passenger/baggage/freight/maintenance service is not possible.
- (4) The ACFT in stand NR.301 should be pushed back to face northeast on P5.
- (5) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

