

TEL : 82-32-880-0256
FAX : 82-32-889-5905
AFS : RKRRYNYX
E-mail : aisd@molit.go.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 7/18
7 JUN 2018

GEN : NIL

ENR : NIL

A D : Busan/Gimhae INTL(RKPK)

RWY 36R/18L CLOSED DUE TO CONSTRUCTION

1. INTRODUCTION

RWY 36R/18L is closed due to construction for BAK-14 installation.

2. PERIOD

From 1500 UTC 31 JUL 2018 To 1500 UTC 19 OCT 2018

3. RESTRICT ROUTE

See the diagram

4. REMARKS

- (1) During work periods, pilots should use caution instructions near the working area.
- (2) Work by equipment and vehicles will be conduct in the working area.
- (3) Aircrafts can cross RWY 36R/18L for using RWY 36L/18R.
- (4) Any change to the contents of this page will be notified by NOTAM.

5. DIAGRAM

