TEL: 82-32-880-0256 FAX: 82-32-889-5905

AFS: RKRRYNYX

E-mail: aisd@molit.go.kr Web: http://ais.casa.go.kr

REPUBLIC OF KOREA

Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP

Supplement 11/19

6 JUN 2019

GEN: NIL

ENR: NIL

A D: SEOUL/Incheon INTL(RKSI)

TWY CLOSED DUE TO THE APRON CONSTRUCTION


1. INTRODUCTION

TWY M(between M17 and M19), M18, M19 and TWY R17(between ACFT stand NR. 812 and 813) will be closed for new apron construction.

2. PERIOD

Restriction	Period(UTC)	
TWY M(between M17 and M19), M18, M19 Close ** No effect on TWY M17 operation.	From 1600 UTC 20 JUN 2019 To 1600 UTC 1 AUG 2019	
TWY M(between M17 and M19), M18, M19, R17(between ACFT stand NR 812 and 813) Close	From 1600 UTC 1 AUG 2019 To 0900 UTC 30 NOV 2019	
TWY M(between M17 and M19), M18, M19 Close * No effect on TWY M17 operation.	From 0900 UTC 30 NOV 2019 To 0900 UTC 31 DEC 2019	

3. WORKING AREA (Refer to the diagram)



Working Area			
No	Position		
1	37°28'39.04"N	126°25'03.24"E	
2	37°28'36.93"N	126°25'01.90"E	
3	37°28'35.32"N	126°24'58.18"E	
4	37°28'27.46"N	126°25'04.15"E	
5	37°28'27.46"N	126°25'06.70"E	
6	37°28'12.78"N	126°25'18.55"E	
7	37°28'11.57"N	126°25'22.86"E	
8	37°28'16.23"N	126°25'31.32"E	
9	37°28'17.96"N	126°25'29.59"E	
10	37°28'21.26"N	126°25'35.55"E	
11)	37°28'22.56"N	126°25'34.17"E	
12	37°28'46.79"N	126°25'21.22"E	

4. REMARKS

- (1) Taxiways will be closed as shown in the diagram.
- (2) Some parts of Standard taxi routes(AIP RKSI AD CHART 2-6 & 2-8) and Low visibility procedure (AIP RKSI AD 2-31 & 2-32) will be temporarily changed due to the construction.
- (3) Taxi routes will be changed as shown in the diagram.
- (4) Works by equipment & vehicles will be conducted in the working area.
- (5) Any change to the contents of these pages will be notified by NOTAM.

(AIRAC AIP SUP 7/19 is hereby superseded)

5. DIAGRAMS

