TEL: 82-32-880-0256 FAX: 82-32-889-5905

AFS: RKRRYNYX E-mail: aisd@molit.go.kr Web: http://ais.casa.go.kr

# REPUBLIC OF KOREA

# Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP

Supplement 18/20

27 AUG 2020

**GEN: NIL** 

**ENR: NIL** 

A D: MUAN/Muan INTL(RKJB)

## **TEMPORARY OBSTACLE ERECTED**

### 1. INTRODUCTION

The obstacle will be installed at the east side of Muan INTL Airport RWY 01 threshold due to work in progress.

\* The obstacle is located at 113.5 m south and 175 m east of RWY 01 threshold.

#### 2. PERIOD

From 1500 UTC 26 AUG 2020 To 1500 UTC 31 DEC 2020

#### 3. WORKING AREAS


No.	Position	No.	Position
1)	34°58'40.7992"N 126°23'4.1300"E	2	34°58'40.8148"N 126°23'7.4781"E
3	34°58'39.1863"N 126°23'7.4937"E	4	34°58'39.1766"N 126°23'4.1621"E

## 4. REMARKS

- (1) Work by equipments and vehicles will be conducted in the area as shown in diagram.
- (2) Equipments and vehicles for work will penetrate approach surface. [The obstacle height is about 5 m(16.4 ft)]
- (3) Any change to the contents of these pages will be notified by NOTAM.

(NOTAM A0988/20 NOTAMN is hereby superseded)

# 5. DIAGRAM



No.	Position		
1	34°58'40.7992"N 126°23'4.1300"E		
2	34°58'40.8148"N 126°23'7.4781"E		
3	34°58'39.1863"N 126°23'7.4937"E		
4	34°58'39.1766"N 126°23'4.1621"E		

