

TEL : 82-32-880-0256  
 FAX : 82-32-889-5905  
 AFS : RKRRYNYX  
 E-mail : aisd@molit.go.kr  
 Web : http://ais.casa.go.kr

# REPUBLIC OF KOREA

Ministry of Land, Infrastructure and Transport  
 Office of Civil Aviation  
 11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP

Supplement 16/20  
 27 AUG 2020

**GEN : NIL**

**ENR : NIL**

**A D : SEOUL/Incheon INTL(RKSI)**

## TEMPORARY OBSTACLE ERECTED

### 1. INTRODUCTION

The obstacle will be installed at the east side of RWY 15L/33R of Incheon INTL Airport.  
 ※ The OBST is located about 4 169 m to the east from the centerline of RWY 15L/33R.

### 2. PERIOD

From 1500 UTC 29 AUG 2020 To 1500 UTC 30 AUG 2021


### 3. WORKING AREAS

Position		OBST Type	Height		Remarks
			AGL	AMSL	
37°28'56.78580"N	126°30'01.09128"E	Tower Crane	86.98 m	98.48 m	Marked and Lighted
37°28'53.95041"N	126°30'02.55552"E		79.10 m	90.60 m	
37°28'55.30226"N	126°30'05.54190"E		80.45 m	91.95 m	
37°28'56.19144"N	126°30'04.14709"E		77.11 m	88.61 m	
37°28'57.12170"N	126°30'07.26824"E		74.34 m	85.84 m	
37°28'59.37946"N	126°30'09.37227"E		64.59 m	76.09 m	
37°28'59.37612"N	126°30'03.77728"E		79.24 m	90.74 m	
37°28'59.09376"N	126°29'59.73429"E		75.96 m	87.46 m	

### 4. REMARKS

- (1) Tower crane turns on its axis(Radius 70 m).
- (2) This tower crane penetrates the conical surface of RKSI.
- (3) Lights will be installed on the top of the every tower crane.
- (4) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM



NOT TO SCALE