

TEL : 82-32-880-0256
FAX : 82-32-889-5905
AFS : RKRRYNYX
E-mail : aisd@molit.go.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 25/20
19 NOV 2020

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

TEMPORARY OBSTACLES ERECTED

1. INTRODUCTION

Temporary obstacles will be existing on the north side of RWY 16/34 of Incheon INTL Airport.

※ The obstacles are located about 1 188 m north from the threshold of RWY 16/34.

2. PERIOD

From 0900 UTC 27 NOV 2020 To 0900 UTC 31 OCT 2021

3. WORKING AREAS

	Position		OBST Type	Height		Radius	Remarks
				AGL	AMSL		
①	37°28'59.92"N	126°24'15.98"E	Pump cars Cranes Cargo cranes	20.0 m	24.5 m	30 m	Marked
②	37°29'10.41"N	126°24'34.29"E		20.0 m	24.5 m	30 m	Marked
③	37°28'51.07"N	126°24'23.43"E		20.0 m	24.5 m	30 m	Marked
④	37°29'01.32"N	126°24'42.43"E		20.0 m	24.5 m	30 m	Marked

4. REMARKS

- (1) Each crane turns on its axis.
- (2) Works will be conducted by equipments and vehicles in the area as shown in the diagram.
- (3) These cranes do not penetrate the approach, transition and horizontal surface of RKSI.
- (4) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

