

TEL : 82-53-668-0255
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aais@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 2/21
11 FEB 2021

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

ACFT STANDS CLOSED DUE TO REMOTE BOARDING FACILITY CONSTRUCTION

1. INTRODUCTION

ACFT stands NR. 352, 353, 354 will be closed due to remote boarding facility construction.

2. PERIOD

From 1500 UTC 25 MAR 2021 To 1400 UTC 25 MAR 2022

3. WORKING & CLOSED AREA (See the diagram)

No.	Position		Closed Areas
①	37°27'59.33"N	126°25'34.90"E	ACFT stands NR. 352, 353, 354 ※ No effect on ACFT stands NR. 351 and 355 operations.
②	37°27'59.50"N	126°25'35.21"E	
③	37°28'00.54"N	126°25'35.49"E	
④	37°28'01.40"N	126°25'37.02"E	
⑤	37°27'55.82"N	126°25'42.24"E	
⑥	37°27'55.08"N	126°25'40.97"E	
⑦	37°27'53.53"N	126°25'40.72"E	
⑧	37°27'53.27"N	126°25'40.30"E	

4. REMARKS

- (1) Safety fence will be installed to indicate the working area.
- (2) This work has no effect on TWY R4 normal operation.
- (3) Work by equipments and vehicles will be conducted in the area as shown in the diagram.
- (4) Equipments and vehicles do not penetrate obstacle limitation surfaces.
- (5) During the work period, pilots should exercise caution and follow ATC's instruction when taxiing ACFT near the working area.
- (6) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

